



## GLOBAL JET MANAGEMENT LLC

www.globaljetmanagementllc.com

[cv1962@aol.com](mailto:cv1962@aol.com)

(972)342-3750

### 2006 HAWKER 850XP

Serial Number: 258784

Registration Number N850RC

AIRFRAME, ENGINES & APU - Times Current as of 10/30/15

AFTT: 2043

Landings: 1336

	<u>Engine 1</u>	<u>Engine 2</u>	<u>APU</u>
Model:	TFE731-5BR	TFE731-5BR	GTCP36-150W
Serial Number:	P-129220	P-129218	P-909
Time Since New:	1638.9	1638.9	1592
Cycles Since New:	1149	1149	
Maintenance Plan:	MSP GOLD	MSP GOLD	FRESH MPI's

#### AVIONICS

Collins Proline 21 Avionics System

Dual Collins VHF-4000 COMM's

Dual Collins NAV-4500 NAV's

Dual Collins DME-4000

Dual Collins ADF-4500

Dual Honeywell FMS 6000

Dual Collins GPS-4000A

Dual Collins AHC-3000 AHRS

Collins AFD-3010/AFD-3010E AFIS

Collins TCAS TTR 4000

Dual Collins FGC-3000 Flight Director System

Dual Meggit MK2 Standby Systems Indicators

Collins TDR-94D Mode S (L/R)

Collins FGC 3000 Autopilot

Collins RTA-858 Radar

Dual Collins ADC 3000 Air Data System

Artex 406 MHZ ELT

Honeywell Mk V EGPWS

Safe Flight (SSU) AOA System

Dual Collins ALT 4000 Radio Alt System

Collins DBU-5000 Nav Data Loader  
Universal CVR 120

Dual NAT System 803-004 Cockpit Audio System  
Dual Collins HF 9000 HF System

#### ADDITIONAL FEATURES

Two owners, US Aircraft  
Rockwell Collins Cabin Management System  
XM Weather

Rosen Sunvisor Kit  
Rockwell Collins IFIS-5000  
Iridium AirCell ST 3100 Flight Phone

#### EXTERIOR

Overall off-white with Black/Gold Metallic

#### INTERIOR

8-Passenger fire-blocked executive interior, including forward, 4-place club, aft-RH, forward facing seat opposite LH, 3-place divan all covered in beige leather. Light cherry high-gloss finish on all cabinetry, the drink rail, all fold-out tables, and bulkheads, including the forward galley which features a microwave and coffee maker. Bright work features an aged bronze finish. Cabin audio/video entertainment system with 5 CD changer, DVD and Airshow 4000 system which is displayed on both forward and aft LCD monitors.

#### MAINTENANCE

New Cockpitt Windshield – 2015  
G Inspection HB-Indy August, 2014

#### STANDARD OPTIONS

AV340	US Weather with ACARS in-flight communication services
AV290	3D FMS Mapping
AV300	Paperless cockpit
AV205	Aircell ST3100 Iridium phone system w/cordless headsets
CE150	Cabin audio and video entertainment system
CE25	Airshow 410 system
CE30	Airshow briefer system
CE75	2 <sup>nd</sup> 15" LCD monitor
CE90	Display computer on cabin monitor
CE115	110 VASC power outlet in cockpit
MS20	Long range oxygen
MS41	Precise flight Pulselite system w/TCAS Interface
MS45	LoPresti high intensity discharge landing and taxi lights
MS50	Dual panel cockpit doors
MS80	Divan fold-out table center seat cushion

MS100	4 each additional storage drawers under cabin seats
MS110	5 each drop-down inboard armrests
MS120	Magazine rack installed on L/H forward bulkhead aft side galley
MS150	Belted lavatory seat
MS220	Flight crew nameplate and holder

#### NON-STANDARD OPTIONS

Divan center back cushion to be easily removable with pip pins

Vestibule rug to run from Jeppesen box to aft side of galley, backed with Johnsonite material, post and eyelet on forward end

Standard set of throw rugs to be backed with Johnsonite material

Extra insulation to be installed from emergency hatch aft

Provide footman loops and netting for divan stowage

Access panels on wing root fairings to have stainless steel camlocks and/or Dzus fasteners as appropriate

Install stainless steel fasteners in exterior access panels

Replace large slotted screws in main wheel wells with "AN" bolts

Replace coin-slot fasteners with Philips-head in access panels

Stainless steel fasteners in O2 service panels

Move cockpit cup holders forward

Add removable panel to vanity two-drawer storage closeout above potty seat to access environmental equipment

**\*\*ASKING PRICE: MAKE OFFER\*\***

The preceding preliminary information is for discussion purposes only. Is subject to change without notice, and is not considered a representation of this aircraft. Interested parties should rely upon their own inspection of the aircraft and its records. Aircraft is offered subject to prior sale or withdrawal from market.